



North Dakota Office of the State Fire Marshal (ND)

INCIDENT REPORT

Official Law Enforcement Report - Unauthorized Dissemination is Prohibited

Incident Type: Fire / Incendiary / Unknown

Agency Incident ID: NDSFM25-025

BATS ID: 1555839

Investigation Title: OAKES PAHL FIRE



Incident Date/Time/Location

Status

Investigation Closed

Jurisdiction

Primary

Start Date/Time

3/11/2025 20:09 Tuesday

Address

9801 98th St SE

City/State/Zip

Oakes, ND 58474

County

Dickey County

Investigator Information

Name

Nicholas J Fettig

Phone

701-955-3294

Email

njfettig@nd.gov

Title

Deputy State Fire Marshal

Property Use or Target Information

Type

Residential

Subtype

1 (Single Family) or 2 Family Dwelling

Status

Occupied And Operating



North Dakota Office of the State Fire Marshal (ND)

INCIDENT REPORT

Official Law Enforcement Report - Unauthorized Dissemination is Prohibited

Incident Type: Fire / Incendiary / Unknown

Agency Incident ID: NDSFM25-025

BATS ID: 1555839

Investigation Title: OAKES PAHL FIRE



Scene Details

Miscellaneous Information

Latitude

45.994072

Longitude

-98.237123



North Dakota Office of the State Fire Marshal (ND)

INCIDENT REPORT

Official Law Enforcement Report - Unauthorized Dissemination is Prohibited

Incident Type: Fire / Incendiary / Unknown

Agency Incident ID: NDSFM25-025

BATS ID: 1555839

Investigation Title: OAKES PAHL FIRE



Person/Organization Information

Name

PAHL, DAVID

DOB

1985

Sex

M

Juvenile

No

Relationship(s)

Occupant, Victim

Race

White

Ethnicity

Non-Hispanic

Age at time of Incident

39



North Dakota Office of the State Fire Marshal (ND)

INCIDENT REPORT

Official Law Enforcement Report - Unauthorized Dissemination is Prohibited

Incident Type: Fire / Incendiary / Unknown

Agency Incident ID: NDSFM25-025

BATS ID: 1555839

Investigation Title: OAKES PAHL FIRE



Name

PAHL, TIM

DOB

1959

Race

White

Ethnicity

Non-Hispanic

Sex

M

Age at time of Incident

65

Juvenile

No

Relationship(s)

Victim



North Dakota Office of the State Fire Marshal (ND)

INCIDENT REPORT

Official Law Enforcement Report - Unauthorized Dissemination is Prohibited

Incident Type: Fire / Incendiary / Unknown

Agency Incident ID: NDSFM25-025

BATS ID: 1555839

Investigation Title: OAKES PAHL FIRE



Name

JORGENSEN, WILLIAM

Juvenile

No

Relationship(s)

Firefighter – Volunteer Dept

Notes

Captain of the Oakes
Fire Department



North Dakota Office of the State Fire Marshal (ND)

INCIDENT REPORT

Official Law Enforcement Report - Unauthorized Dissemination is Prohibited

Incident Type: Fire / Incendiary / Unknown

Agency Incident ID: NDSFM25-025

BATS ID: 1555839

Investigation Title: OAKES PAHL FIRE



Name

HOLLINGSWORTH, JERRY

Juvenile

No

Relationship(s)

Firefighter – Volunteer Dept

Notes

Fire Chief of Oakes
Fire Department



North Dakota Office of the State Fire Marshal (ND)

INCIDENT REPORT

Official Law Enforcement Report - Unauthorized Dissemination is Prohibited

Incident Type: Fire / Incendiary / Unknown

Agency Incident ID: NDSFM25-025

BATS ID: 1555839

Investigation Title: OAKES PAHL FIRE



Attachments

Filename	Description	Date
NDSFM25-025-1 OAKES PAHL FIRE.pdf		7/24/2025

No image specified



North Dakota Office of the State Fire Marshal (ND)

INCIDENT REPORT

Official Law Enforcement Report - Unauthorized Dissemination is Prohibited

Incident Type: Fire / Incendiary / Unknown

Agency Incident ID: NDSFM25-025

BATS ID: 1555839

Investigation Title: OAKES PAHL FIRE



Narrative(s)

Title

Distribution List

Author

Nicholas Fettig

7019553294

njfettig@nd.gov

Description

Oakes Fire Department - ofd@drtel.net



North Dakota Office of the State Fire Marshal (ND)

INCIDENT REPORT

Official Law Enforcement Report - Unauthorized Dissemination is Prohibited

Incident Type: Fire / Incendiary / Unknown

Agency Incident ID: NDSFM25-025

BATS ID: 1555839

Investigation Title: OAKES PAHL FIRE



This section intentionally left blank

Deputy State Fire Marshal - Fettig, Nicholas

Date

Approving Official

Date



North Dakota State Fire Marshals Office (ND)

INCIDENT ORIGIN & CAUSE NARRATIVE

Official Law Enforcement Report – Unauthorized Dissemination is Prohibited



Incident Type: FIRE

Agency Incident ID: NDSFM25-025

BATS ID: i-1555839

Investigation Title: OAKES PAHL FIRE

Identify the Need

Call for Service (dispatch, request, date, time):

On Tuesday, March 11, 2025, at approximately 9:00 PM, I Deputy State Fire Marshal (DSFM) Nick Fettig was contacted by the on-call deputy regarding a fire in Oakes, ND. The on-call deputy requested that I contact Fire Chief Jerry Hollingsworth of the Oakes Fire Department. I contacted Fire Chief Jerry Hollingsworth and during the discussion it was agreed that the fire investigation would begin on Wednesday, March 12, 2025, at approximately 10:00 AM.

North Dakota Century Code 18-01-07 states; "An investigation of each fire must be made by the officers required to report the occurrence of fires under section 18-01-06."

Define the Problem

Nature of Incident/Incident Overview:

A fire occurred in a residential mobile trailer home at 9805 103rd Ave SE in Oakes, ND. The fire was reported on March 11, 2025, at approximately 8:09 PM. The Oakes Fire Department responded and extinguished the fire. The property owner was in the shop at the time of the fire and had family members call 911. No injuries or fatalities were reported. (See Figure 1)



North Dakota State Fire Marshals Office (ND)

INCIDENT ORIGIN & CAUSE NARRATIVE

Official Law Enforcement Report – Unauthorized Dissemination is Prohibited



Incident Type: FIRE

Agency Incident ID: NDSFM25-025

BATS ID: i-1555839

Investigation Title: OAKES PAHL FIRE



Figure 1 Photograph NJF_0001 North side of the structure

Authority to Enter/Search:

I arrived on scene on March 12, 2025, at approximately 10:00 AM. I met with Captain William Jorgenson, Oakes Fire Department, Assistant Fire Chief Jeremy Sitzler and property owners David Pahl and Tim Pahl. I presented David Pahl and Tim Pahl with a Consent to Search Form. David Pahl and Tim Pahl reviewed the form and did not have any questions or concerns and agreed to sign the form. Captain William Jorgenson witnessed the discussion and Tim Pahl and David Pahl signing the form. The form will remain with the file.

After a brief discussion with David Pahl and Tim Pahl about safety concerns, I released the scene back to the Oakes Fire Department. I advised David Pahl and Tim Pahl to contact the insurance company prior to altering the scene.

I departed the scene at approximately 2:30 PM.

Assisting Person/Agencies:

Name	Agency	Case Reference if Available
Fire Chief Jerry Hollingsworth	Oakes Fire Department	0172025



North Dakota State Fire Marshals Office (ND)

INCIDENT ORIGIN & CAUSE NARRATIVE

Official Law Enforcement Report – Unauthorized Dissemination is Prohibited



Incident Type: FIRE

Agency Incident ID: NDSFM25-025

BATS ID: i-1555839

Investigation Title: OAKES PAHL FIRE


Fatalities/Injuries:		
Name	Fatality/Injury:	Notes/Other Information
		No injuries or fatalities were reported to the North Dakota State Fire Marshal's Office.

Data Collection

Photographs:

Prior to physically altering the fire scene, the scene was photographed in the condition it was found. During the investigation, layering process and reconstruction process a series of 95 photographs were taken. The photographs and photograph log will remain with the file.

Drawings/Sketches:



Exterior Scene Examination:

During my initial 360° walk around of the structure a Scene Safety Form was completed. The form will remain with the file. The structure was a single wide mobile trailer house with a metal roof and wooden siding. The



North Dakota State Fire Marshals Office (ND)

INCIDENT ORIGIN & CAUSE NARRATIVE

Official Law Enforcement Report – Unauthorized Dissemination is Prohibited



Incident Type: FIRE

Agency Incident ID: NDSFM25-025

BATS ID: i-1555839

Investigation Title: OAKES PAHL FIRE

electrical meter was housed on a utility pole on the south side of the structure with the electrical meter still in place. The Lp tank was located in the west side of the property with the regulator mounted on the tank. The Lp tank gauge read approximately 20% full and the shutoff valve was in the closed position. No fire or smoke damage was observed to the electrical meter and the Lp tank or regulator.

The north side of the structure had received smoke staining to the top portions of the windows with all window glass broken into the structure. The exterior door on the deck was removed prior to arrival on scene and was found on the west side of the deck. The door received mass loss to the top portion of the door and the center glass broke. No damage was observed on the roof. (See Figure 2)



Figure 2 Photograph NJF_0005, North side of structure with door removed

The west side of the structure had received broken glass to the window with smoke staining to the top portion of the wall and window framing. A step ladder was observed placed under the window.

The south side of the structure had all windows broken with smoke staining on the upper portion of the window framing continued up the wall. The mud room addition received smoke staining to the upper portion of the doorway that continued to the siding. The door had glass broken out of the door.

The ground next to the structure was observed with multiple plastic fuel containers and fire debris removed from the structure. This portion of the structure also had appliances, plastic buckets, tires, wooden furniture



North Dakota State Fire Marshals Office (ND)

INCIDENT ORIGIN & CAUSE NARRATIVE

Official Law Enforcement Report – Unauthorized Dissemination is Prohibited



Incident Type: FIRE

Agency Incident ID: NDSFM25-025

BATS ID: i-1555839

Investigation Title: OAKES PAHL FIRE

and chairs. (See figure 3)



Figure 3 Photograph NJF_0011 South side of the structure

The east side of the structure received smoke staining around the window and smoke staining around the top portion of the roof line.

Interior Scene Examination:

My interior scene examination began in the area of least damage and continued to the area of greatest damage. During my initial safety walk through, it was determined that the area of least damage was the furthest west bedroom, and the area of greatest damage was the kitchen.

Entry was made into the structure at the doorway on the deck of the north side of the structure. The bedroom furthest west received smoke staining to the upper half portion of the walls and ceiling. The room was filled with a large portion of wood materials and furniture pieces that made the room unable to fully enter. (See Figure 4)



North Dakota State Fire Marshals Office (ND)

INCIDENT ORIGIN & CAUSE NARRATIVE

Official Law Enforcement Report – Unauthorized Dissemination is Prohibited



Incident Type: FIRE

Agency Incident ID: NDSFM25-025

BATS ID: i-1555839

Investigation Title: OAKES PAHL FIRE



Figure 4 Photograph NJF_0020, West bedroom with storage

The next room was the bathroom. The bathroom received smoke staining to the upper half portions of the walls and ceiling. The shower wall panels received melting and deformation to the plastic structural support from top down. A wooden dresser with a flat screen television was observed in the bathroom. The television had received melting to the top portion of the television.

The open area received smoke staining to the walls and ceiling. Wallpaper on the east wall showed charring and deformation. The light fixtures from the ceiling were missing with exposed wiring observed in place. A large amount of items were observed such as wooden furniture, plastic totes, and card board boxes. (See figure 5)



North Dakota State Fire Marshals Office (ND)

INCIDENT ORIGIN & CAUSE NARRATIVE

Official Law Enforcement Report – Unauthorized Dissemination is Prohibited



Incident Type: FIRE

Agency Incident ID: NDSFM25-025

BATS ID: i-1555839

Investigation Title: OAKES PAHL FIRE



Figure 5 Photograph NJF_0024, Open area with smoke staining and charring to wall paper.

The living room received mass loss of insulation and gypsum board. Mass loss to roof trusses at the center point with charring from bottom up along the rest of the trusses. A ceiling fan was observed in the center of the room still connected by the wiring and mass loss of the fan blades and oxidation to the motor housing. Furniture in the living room was observed as a couch and mattress that both sustained mass loss and charring from east to west. A large amount of items were observed in the living room as of wooden furniture pieces, mattress, dog kennel, couch, paper and cloth materials, cardboard and plastic containers. (See figure 6)



North Dakota State Fire Marshals Office (ND)

INCIDENT ORIGIN & CAUSE NARRATIVE

Official Law Enforcement Report – Unauthorized Dissemination is Prohibited



Incident Type: FIRE

Agency Incident ID: NDSFM25-025

BATS ID: i-1555839

Investigation Title: OAKES PAHL FIRE



Figure 6 Photograph NJF_0028 Living Room, south wall.

The bathroom on the east side of the structure sustained smoke staining to the walls and ceiling. The shower walls sustained melting and deformation to the plastic supports. Connected to the bathroom was a bedroom that sustained smoke staining to the upper half portion of the walls. The ceiling sustained smoke staining and partial collapse of the gypsum boards exposing heating ventilation and air conditioning (HVAC) ducting and insulation. The electrical breaker box was located in the northwest corner of the room but was unable to examine it due to the large amount of materials located in the bedroom. Material located in the east bedroom are of the following, wooden furniture, mattress, cloth materials and large amount of wood planks.

The mechanical room received smoke staining to the upper half portion of the walls. Mass loss of gypsum boards for the ceiling with charring to the wooden rafters. Appliances in this room are of the following washing machine, dryer, water heater and furnace. The water heater and furnace sustained smoke staining and melting of plastic components from top down.

The mudroom sustained smoke staining to the upper half portion of the walls and ceiling. A large amount of wooden planks and particle boards were stored in the room along with black plastic garbage bags and plastic containers.



North Dakota State Fire Marshals Office (ND)

INCIDENT ORIGIN & CAUSE NARRATIVE

Official Law Enforcement Report – Unauthorized Dissemination is Prohibited



Incident Type: FIRE

Agency Incident ID: NDSFM25-025

BATS ID: i-1555839

Investigation Title: OAKES PAHL FIRE

The kitchen sustained smoke staining to the walls and ceiling. The east wall received mass loss of the gypsum boards and mass loss of three wall studs with smoke staining to the wall studs at counter top level. On the north side a line of demarcation was discovered on the lower portion of the cabinets with charring on the top portion of the cabinets. On the counter space located near the stove on the right-hand side multiple lithium-ion batteries and battery sheets were discovered with multiple cigarettes filter ends found. (See figure 7)



Figure 7 Photograph NJF_0069 Lithium-ion battery sheets discovered in kitchen

On the west wall behind the stove received mass loss of gypsum boards and charring to the wall studs at countertop level. Electrical wiring received mass loss of electrical wiring insulation and melting of plastic materials. A second refrigerator was found in the center of the kitchen that sustained color changing oxidation to all sides of the refrigerator. All appliances found on counter tops in the kitchen sustained melting and deformation of the plastic housing with the exhaust ventilation of the kitchen hood collapsed on top of the stove. The layering process revealed protected spaces to appliances that were on the kitchen counter tops. The countertops received charring and smoke staining. The kitchen counter top in front of the sink received mass loss to the counter.

Interview #1:	
Name:	David Pahl
Interview Date:	03.12.2025



North Dakota State Fire Marshals Office (ND)

INCIDENT ORIGIN & CAUSE NARRATIVE

Official Law Enforcement Report – Unauthorized Dissemination is Prohibited



Incident Type: FIRE

Agency Incident ID: NDSFM25-025

BATS ID: i-1555839

Investigation Title: OAKES PAHL FIRE

Notes: David Pahl was the occupant of the residential structure at the time of the fire. The following are notes from an informational non-custodial non-recorded interview with David Pahl. The interview took place in the driveway of the property. I informed David Pahl that David Pahl did not have to answer any questions, and that David Pahl could leave at any time.

David Paul stated that David Paul had lived in the structure since 1994. David Paul stated David Paul's parents owned the structure and property. David Paul stated in 2012 David Paul's parents moved out of the structure to the other house on the property. David Paul stated David Paul did smoke inside of the structure and smoked Eagle Blues 20s. David Paul stated David Paul would extinguish the cigarettes into ash trays throughout the structure.

David Paul stated to have no mechanical or electrical issues with the structure except having a refrigerator that went bad but was unplugged. David Paul stated that David Paul did not have any enemies that would want to cause David Paul harm.

David Paul stated that on the night of the fire David Paul was inside of the structure cooking dinner and when finished David Paul went to the shop to work on tires. David Paul stated when David Paul went outside of the shop David Paul could see flames and smoke at the structure. David Paul stated David Paul ran to the structure to get David Paul's dog out of the structure and noticed flames inside the kitchen area. David Paul stated that David Paul went to Tim and Barb Paul's home to tell them to call 911 and left David Paul's dog at Tim Paul and Barb Paul's home. David Pahl stated that David Pahl was the only person at the structure the night of the fire.

Interview #2:

Name: Tim Pahl

Interview Date: 03.12.2025

Notes: Tim Pahl was the owner of the residential structure at the time of the fire. The following are notes from an informational non-custodial non-recorded interview with Tim Pahl. The interview took place in the driveway of the property. I informed Tim Pahl that Tim Pahl did not have to answer any questions, and that Tim Pahl could leave at any time.

Tim Paul stated that Tim Paul purchased the mobile home in 1994. Tim Paul stated in 2012 Tim Paul and Barb Paul moved out of the structure and to another structure on the property in 2012. Tim Paul stated that David Paul had trouble paying bills, so Tim Paul paid all bills associated with this structure including the insurance. Tim Paul stated that Tim Paul and David Paul had no leasing agreement made for staying in this structure and that David Paul would help out on the farm when Tim Paul needed it.

Tim Paul stated on the night of the fire David Paul dropped David Paul's dog off at Tim Paul's home and stated David Paul's home was on fire and to call 911. Tim Paul stated that David Paul's dog smelt like smoke and burned electrical wiring.

Tim Paul stated Tim Paul and David Pahl did not have any issues with David Paul living in the structure and Tim Paul stated that David Paul was Tim Pahl's son and was there to help David Pahl out.



North Dakota State Fire Marshals Office (ND)

INCIDENT ORIGIN & CAUSE NARRATIVE

Official Law Enforcement Report – Unauthorized Dissemination is Prohibited



Incident Type: FIRE

Agency Incident ID: NDSFM25-025

BATS ID: i-1555839

Investigation Title: OAKES PAHL FIRE

Tim Pahl was not aware of any mechanical or electrical issues with the structure except for a refrigerator that went out. Tim Pahl stated that Tim Paul helped David Pahl move in a new refrigerator.

Tim Pahl provided property insurance documentation with the following information was obtained from the insurance policy documents.

Property Insurance Policy

- Farmers Union Insurance in Ellendale, ND.
- Policy Number FR00071980-09
- \$5,000 limit on structure.

Interview #3:

Name: Captain William Jorgenson

Interview Date: 03.12.2025

Notes: Captain William Jorgenson was the Captain of the Oakes Fire Department at the time of the fire. The following are notes from an informational non-custodial non-recorded interview with Captain William Jorgenson. The interview took place in the driveway of the property. I informed Captain William Jorgenson that Captain William Jorgenson did not have to answer any questions, and that Captain William Jorgenson could leave at any time.

Captain William Jorgenson stated that the Oakes Fire Department was responding to another call a couple of miles away when Captain William Jorgenson received another page for a structure fire. Captain William Jorgenson stated that when Captain William Jorgenson arrived on scene Captain William Jorgenson seen heavy smoke and flames coming out of the windows on the North side of the structure. Captain William Jorgenson stated fire crews extinguished the fire and broke windows to ventilate the structure.

Video:

No video was available or reviewed by the North Dakota State Fire Marshal's Office.

Weather Reviewed:

The weather information was obtained from www.underground.com. The data was reviewed for March 11, 2025. The closest reporting station was the Aberdeen Regional Airport Station, approximately 46 miles away. The following information was learned. The weather was not a contributing factor of ignition to this fire.

Time	Temperature	Humidity	Wind	Condition
3:53 PM	46°F	24%	16 MPH	Fair
4:53 PM	46°F	24%	17 MPH	Fair
5:53 PM	46°F	29	13	Fair
6:53 PM	44°F	31	10	Fair
7:53 PM	38°F	39	7	Fair



North Dakota State Fire Marshals Office (ND)

INCIDENT ORIGIN & CAUSE NARRATIVE

Official Law Enforcement Report – Unauthorized Dissemination is Prohibited



Incident Type: FIRE

Agency Incident ID: NDSFM25-025

BATS ID: i-1555839

Investigation Title: OAKES PAHL FIRE

8:53 PM	34°F	46	9	Fair
9:53 PM	34°F	48	7	Fair
10:53 PM	28°F	61	7	Fair

Times:		
Hard Time Description	Time	Soft Time Description
	7:00 PM	Last time David Pahl was inside of the structure.
	8:00 PM	Fire Discovered by David Pahl
Time of 911 Call	8:09 PM	
Fire Department Dispatched	8:10 PM	
Fire Department on Scene	8:18 PM	
Fire Marshal's Office Requested	9:03 PM	
Oakes Fire Department Cleared Scene	11:03 PM	

Evidence identified/collected/preserved:
No evidence was identified, collected, or preserved by the North Dakota State Fire Marshal's Office.

Data Analysis, hypothesis development, hypothesis testing, select final hypothesis

Other Forms/Documents/Reports Reviewed:
Call For Service Detail Report ● 911 call came in at 8:09 PM. ● Oakes Fire Department was paged at 8:10 PM. ● Oakes Fire Department arrived on scene at 8:18 PM. ● Fire Marshal's Office was requested at 9:03 PM ● Oakes Fire Department cleared scene at 11:03 PM.



North Dakota State Fire Marshals Office (ND)

INCIDENT ORIGIN & CAUSE NARRATIVE

Official Law Enforcement Report – Unauthorized Dissemination is Prohibited



Incident Type: FIRE

Agency Incident ID: NDSFM25-025

BATS ID: i-1555839

Investigation Title: OAKES PAHL FIRE

911 Call Recording

- Caller reported the kitchen was on fire.
- Caller was told to call 911 by son.

Property Insurance Policy

- Farmers Union Insurance in Ellendale, ND.
- Policy Number FR00071980-09
- \$5,000 limit on structure.

Area of Origin:

Based on the fire scene examination, witness statements, and other data reviewed, the area of origin was determined to be in the kitchen. (See figure 8)



Figure 8 Photograph NJF_0052 Kitchen

• Fire Effects

- This area sustained the most consumption compared to the rest of the structure.
- The wood framing sustained more charring and mass loss compared to the rest of the structure.
- The entire ceiling of gypsum boards was collapsed in this area compared to the rest of the structure.



North Dakota State Fire Marshals Office (ND)

INCIDENT ORIGIN & CAUSE NARRATIVE

Official Law Enforcement Report – Unauthorized Dissemination is Prohibited



Incident Type: FIRE

Agency Incident ID: NDSFM25-025

BATS ID: i-1555839

Investigation Title: OAKES PAHL FIRE

- **Fire Dynamics**

- Mass loss of gypsum boards in the walls in the kitchen.
- Color changing oxidation to the secondary refrigerator.
- Charring and mass loss to wall studs in the area of the kitchen.
- Charring and mass loss to the rafters in the kitchen area.

- **Witness Statement**

- David Pahl stated that David Pahl seen flames coming from the kitchen.
- 911 caller stated kitchen was on fire.
- Captain William Jorgenson stated that Captain William Jorgenson seen flames in the kitchen.

Cause Hypothesis Development and Testing:

The following were identified as the most credible potential fire cause within the area of origin:

- **A person or persons unknown entered the structure utilized an open flame source to ignite ordinary combustible materials.**

- Materials observed in the structure included paper, cardboard, plastics, and cloth.
- David Pahl stated David Pahl was on the property at the time of the fire.
- David Pahl stated that no other person was at the residence at the time of the fire.
- Captain William Jorgenson stated that Captain William Jorgenson only seen Tim Pahl and David Pahl at the structure the night of the fire.
- David Pahl stated no enemies that would want to cause David Pahl harm.
- This hypothesis could not be eliminated.

- **Improperly discarded smoking material igniting available ordinary combustible material.**

- Materials observed in the structure included paper, cardboard, plastics, and cloth.
- David Pahl stated that David Pahl smoked inside of the structure.
- Cigarette filter ends were observed on kitchen countertops.
- This hypothesis could not be eliminated.

- **An unattended cooking appliance was left on creating enough heat to ignite ordinary combustible material.**

- David Pahl stated that David Pahl made food in the kitchen before working in the shop.
- The area with the most damage was determined to be in the kitchen of the structure.
- The cooking appliances on the countertops sustained mass loss and deformation.
- This hypothesis could not be eliminated.

Final Hypothesis/Conclusion:

Based on the fire scene examination, witness statements, and other data reviewed, the area of origin was determined to be in the kitchen. Due to the mass loss and the overabundance of household items limiting



North Dakota State Fire Marshals Office (ND)

INCIDENT ORIGIN & CAUSE NARRATIVE

Official Law Enforcement Report – Unauthorized Dissemination is Prohibited



Incident Type: FIRE

Agency Incident ID: NDSFM25-025

BATS ID: i-1555839

Investigation Title: OAKES PAHL FIRE

access into multiple rooms and also multiple hypothesis that could not be eliminated the fire cause remains undetermined.

The fire was classified as undetermined.

The opinions expressed in this conclusion are based on data and evidence collected to this point. The opinions are subject to change based upon relevant, significant and credible information discovered or provided in the future.

References:

Technical Committee on Fire Investigations. 2023. NFPA 921: Guide for Fire & Explosion Investigations. 2024 Edition. NFPA. Quincy, MA



Photograph Log
 NORTH DAKOTA INSURANCE DEPARTMENT
 NORTH DAKOTA STATE FIRE MARSHAL

Fire Investigation #	NDSFM25-025-1	Date Photos taken	03.12.2025
Photographer	DSFM Nick Fettig		
Archive #/other identifier	NJF_0001 – NJF_095 Direction is the direction the photographer was facing.		

Photo #:	Direction:	Description:
0001	S	North side of structure, smoke staining on top portion of all windows, all windows broken, door removed.
0002	S	North side of structure, small patch of charred sticks
0003	S	North side of structure, opening to crawl space, windows broken, smoke staining on top portion of the windows. Gas can near structure.
0004	S	North side of structure, windows broken, smoke staining on top portion of the windows. Walk in door removed.
0005	S	North side of structure, windows broken, smoke staining on top portion of the windows. Walk in door removed.
0006	E	West side of structure, window broken with smoke staining on top portion of the window and siding
0007	E	West side of the structure with Lp tank in yard
0008	E	Lp tank with service lid open, pressure regulator and valve in closed position
0009	E	Lp tank, approximately 15% full
0010	N	South side of structure, windows broken with smoke staining on the upper portions of window and siding.
0011	N	South side of structure, windows broken with smoke staining on the upper portions of window and siding. Debris in yard charred wooden furniture, with many gas cans in yard.
0012	N	South side of yard, charred wooden furniture with microwave with color changing oxidation and deformation
0013	N	South side of yard, charred wooden furniture
0014	N	South side of structure, window broken with smoke staining above window on siding, wooden boards with charring and mass loss
0015	S	South side of yard, gas cans and charred insulation, large appliance
0016	N	South side of yard with gas can and insulation with charring, plastic totes with debris
0017	N	South side of structure, smoke staining to top portion of walk-in door with glass broken, window broken on structure with smoke staining on top portion of window, microwave in front yard with patio furniture, rim and tire.

600 East Boulevard Ave, Bismarck, ND 58505
 Phone: (701)328-5555
 Email: info@nd.gov

0018	N	South side of structure, smoke staining to top portion of walk-in door with glass broken, window broken on structure with smoke staining on top portion of window, microwave in front yard with patio furniture, rim and tire and grill.
0019	W	East side of structure, smoke staining to top portion of walk-in door with glass broken, window broken on structure with smoke staining on top portion of window
0020	W	West bed room, broken window with smoke staining on window, walls and ceiling, wooden furniture stacked in room with large amount of wooden boards in the room. Line of demarcation around the top half of the walls.
0021	S	West bed room, broken window with smoke staining on window, walls and ceiling, wooden furniture stacked in room with large amount of wooden boards in the room. Line of demarcation around the top half of the walls.
0022	S	West bathroom, deformation of shower walls, smoke staining on the walls and ceiling, wooden dresser with television found with smoke staining.
0023	N	Hallway, window broken, smoke staining on all walls and ceiling, large pieces of particle board found on the floor.
0024	S	Open area, wooden furniture stacked, smoke staining to all walls and ceiling, plastic totes and cloth material, electrical wiring in ceiling with no fixtures. Charring to wall paper on walls
0025	S	Open area, wooden furniture stacked, smoke staining to all walls and ceiling, plastic totes and cloth material, electrical wiring in ceiling with no fixtures. Charring to wall paper on walls
0026	E	Open area, wooden furniture stacked, smoke staining to all walls and ceiling, plastic totes and cloth material, electrical wiring in ceiling with no fixtures. Charring to wall paper on walls
0027	S	Living room, mass loss to gypsum boards on ceiling and insulation. Charring to wooden rafters with sections of mass loss. Mattress with mass loss and charring. Smoke staining to all walls and ceiling, charring to wooden furniture.
0028	S	Living room, mass loss to gypsum boards on ceiling and insulation. Charring to wooden rafters with sections of mass loss. Mattress with mass loss and charring. Smoke staining to all walls and ceiling, charring to wooden furniture.
0029	S	Living room, mass loss to gypsum boards on ceiling and insulation. Charring to wooden rafters with sections of mass loss. Mattress with mass loss and charring. Smoke staining to all walls and ceiling, charring to wooden furniture.
0030	E	Living room, mass loss to gypsum boards on ceiling and insulation. Charring to wooden rafters with sections of mass loss. Smoke staining to all walls and ceiling, charring to wooden furniture.
0031	E	Living room, melting and deformation to plastic housing, charring to wicker basket.
0032	N	Kitchen, mass loss of upper portions of gypsum board, charring to

		wall studs, mass loss of insulation.
0033	E	Kitchen, mass loss of gypsum boards to east wall and ceiling, color changing oxidation to the refrigerator with deformation, charring to wooden rafters,
0034	N	Kitchen, mass loss of gypsum boards to north and east wall
0035	E	Hallway, charring to wall studs and mass loss to insulation
0036	N	Mechanical room, smoke staining to walls and ceiling, color changing oxidation to washer and dryer
0037	E	Mechanical room, water heater, smoke staining to assembly
0038	E	Mechanical room, water heater, smoke staining to assembly
0039	S	Hallway, mass loss and charring to insulation, portable air conditioning unit with mass loss to assembly housing
0040	S	Hallway, charring to wooden furniture, paint cans with the lids open and melting of plastic materials
0041	S	Hallway, charring to wooden furniture, paint cans with the lids open and melting of plastic materials
0042	E	East bedroom, mass loss of upper portion of bed room door, mass loss of gypsum board
0043	N	East bedroom, smoke staining to walls and ceiling, large amount of wooden furniture materials and plastic materials with deformation
0044	N	East bedroom, smoke staining to walls and ceiling, large amount of wooden furniture materials and plastic materials with deformation
0045	E	East bathroom, smoke staining to the walls and ceiling
0046	N	East bathroom, deformation and melting to shower walls, smoke staining to walls
0047	E	East bathroom, plastic containers on the floor with melting and a 5-gallon paint container
0048	W	East bedroom, smoke staining to the walls and ceiling, melting to plastic materials, charring to wooden furniture
0049	W	East bedroom, smoke staining to the walls and ceiling, melting to plastic materials, charring to wooden furniture
0050	W	Kitchen, electrical wiring with mass loss of electrical wiring insulation, mass loss of insulation, charring to wooden furniture
0051	W	Kitchen, stove with color changing oxidation, mass loss to insulation
0052	N	Kitchen, mass loss of gypsum boards to walls, mass loss of insulation
0053	E	Kitchen, mass loss of gypsum boards to north and east walls, color changing insulation to refrigerator
0054	W	Kitchen, oxidation to metal assembly, charring and mass loss to paper plates, charring to wooden furniture
0055	W	Kitchen, oxidation to metal assembly, charring and mass loss to paper plates
0056	W	Kitchen, oxidation to metal assembly
0057	E	Kitchen, charring to wooden furniture, oxidation to metal pans

0058	E	Kitchen, charring to wooden furniture, oxidation to metal pans
0059	E	Kitchen, charring to wooden furniture, oxidation to metal pans, charring to pastas
0060	W	Kitchen, deformation to plastic housing, mass loss of plastic hose
0061	W	Kitchen, deformation to plastic housing, mass loss of plastic hose
0062	W	Kitchen, mass loss and charring to cardboard materials, charring to wooden furniture
0063	N	Kitchen, stove door propped open, mass loss of insulation
0064	W	Kitchen, cardboard box inside of stove with charring to cardboard box
0065	W	Kitchen, stove top with charring and mass loss to pasta material, charring to wooden material
0066	W	Kitchen, layering process of stove top, burner with missing cover
0067	W	Kitchen, layering process of stove top, burner with missing cover, appliance with mass loss of plastic housing
0068	W	Kitchen, layering process of stove top, burner with missing cover, electrical line cord with mass loss of electrical wiring insulation
0069	W	Kitchen, stove top with lithium-ion battery opened with battery sheet
0070	E	Kitchen, lithium-ion batteries and charring to food materials, oxidation to tin cans
0071	E	Kitchen, lithium-ion batteries and charring to food materials, oxidation to tin cans
0072	W	Kitchen, mass loss to plastic housing to Keurig machine
0073	N	Kitchen, mass loss to plastic housing to Keurig machine
0074	N	Kitchen, charring and mass loss to wall stud and insulation
0075	W	Kitchen, mass loss of wiring insulation
0076	W	Kitchen, mass loss of wiring insulation
0077	W	Kitchen, mass loss of wiring insulation
0078	W	Kitchen, mass loss of wiring insulation, plastic housing mass loss
0079	N	Kitchen, witness marking of electrical wiring cut placement
0080	N	Kitchen, witness marking of electrical wiring cut placement
0081	S	Kitchen, Keurig machine with mass loss and deformation of plastic housing
0082	E	Kitchen, layering process of kitchen counter top
0083	N	Kitchen, counterspace with layering process, charring and mass loss to cardboard boxes
0084	W	Kitchen, lithium-ion battery with battery sheet exposed
0085	N	Kitchen, layering process of kitchen counter top
0086	N	Kitchen, mass loss of gypsum board on the west and north wall, mass loss of electrical wiring insulation
0087	N	Kitchen, mass loss of gypsum boards on the ceiling, mass loss to insulation

600 East Boulevard Ave, Bismarck, ND 58505
Phone: (701)328-5555
Email: info@nd.gov

0088	E	Kitchen, multiple aerosol cans found with smoke staining, and mass loss of cardboard materials
0089	N	Kitchen, mass loss of gypsum boards on the north wall, charring to kitchen cabinets,
0090	N	Mudroom, smoke staining to the walls and ceiling, large amount of wooden boards and plastic containers
0091	N	Mudroom, smoke staining to the walls and ceiling, large amount of wooden boards and plastic containers
0092	S	Mudroom, smoke staining to the walls and ceiling, large amount of wooden boards and plastic containers
0093	N	Mudroom, mass loss and charring to wooden ceiling, and smoke staining
0094	N	Utility pole, electrical meter intact and in place with no damage to meter
0095	S	Utility pole, distance from electrical meter to structure